Determination of the Deterioration Characteristics of Facade Materials: A Case Study

Nil Kokulu

Antalya Bilim University, Faculty of Fine Arts and Architecture, Çıplaklı Mh. Akdeniz Blv. Pk:07190 Döşemealtı, Antalya, nil.kokulu@antalya.edu.tr

Abstract. Deterioration of the facade materials of a building and its importance are topics that are not getting the attention that they deserve and need. If a material can't meet its accepted performance criterion during its service life then deterioration may occur on the surface, inside, under or at the structure of the material. Environmental, construction related, and human related agents collaborate with the mechanisms and make an effect which concerns the durability. Therefore, detecting the deteriorations of the materials play an important role for the maintenance planning. This study aims to detect the agents, mechanisms and effects of the deteriorations of a case building. A systematic approach was developed by making literature review. Hostile environmental analysis and building facade inspection have been made by the visual observations on a specific day. Deteriorations occurred at granite, wood composite, aluminum, glass and ceramic materials have been discussed.

Keywords: Environmental Deterioration, Facade Inspection, Agents, Mechanisms, Durability.

1 Introduction

Building components are expected to maintain their required performance levels over their service life. In order to succeed in this process, identifying the environment and the future cause of the deteriorations are a precondition. During the literature reviews, it is seen that facade materials such as granite, wood composite, aluminium, glass and ceramic are exposed to deteriorations as time progresses.

According to Grelk *et al.* (2007), bowed granite cladding is a problem caused by the temperature differences and the moisture. Also, Marie (2013), in her article, states that natural stone facades perform differently over time and the colour of the facade may change according to cracking, dirt, corrosion, carbonation and biological colonization. This change causes visual aesthetic problems and the problems may differ according to person's characteristics.

Morrel *et al.* (2010), state that as a biological agent, white rot fungi and brown rot fungi can easily deteriorate wood in wood plastic composites (WPC) and may cause loss of weight depending on the climate. The most important factor was determined as moisture for fungal decay. They also argue that WPC's bending properties change when exposed to fungi. The authors go on to say that physical agents are also important when deterioration of WPC's is the subject. Although the damage seems like it is on the surface, chemical discoloration occurs beneath the surface and it is very difficult to remove. Also, UV degradation changes the characteristics such as colour, surface composition and mechanical changes of WPC's.

According to Honfi *et al.* (2014), in their article about the glass structure failures, they described two kinds of exposures which are faults and errors. Faults are the physical reason for the failures such as excessive loading, surface damage and moisture, while errors are the logical reason of the exposures such as modelling and calculation errors, poor manufacturing and detailing errors.

doi:10.23967/dbmc.2020.032

Corrosion is most common in metals and observed to some extent in ceramics. Khanam *et al.* (2015), state that corrosion on aluminium has seen because of the saline environment. They state that chloride ions attack to aluminium film and made pits on the top. This causes structural failure of the material.

Besides the obvious problems of breakage, ceramics deteriorate during their service life according to temperature, external loads, vibrations and environment. They may contain soluble salts which can crystallize at or near the surface and destroy the material. Also, unstable glazes of the ceramics may cause crumbs on the surface (Museum Management Programme, 2018).

In this study, the deteriorations formed in granite, wood composite, ceramic, aluminum and glass and their causes have been explained systematically. Agents, mechanisms and effects of the deteriorations were identified. Results and expected damage are explained at the end.

2 The Case Study

2.1 Preparing the Data Analysis

In this section, specific data, information and analysis of the front facade of the building are intended to provide a proper method for conducting the deteriorations. The first part of this section provides a draft of the proposed systematic approach to study that reflects on an individual understanding and perception of the research process. The second part consists the inspections of the hostile environment and the facade of the building. For the hostile environmental analysis, site selection, building information and the climate data were studied. For the facade of the building, facade materials and their structure system were investigated.

2.2 Systematic Approach to Study

A systematic approach is an outline of the researcher for determining the steps of the case study (Figure 1).

Macro environment analysis focuses on the continental observations consisting of location, orientation of the building, surrounding buildings, traffic and pedestrian roads and vegetation at the site. Meso environment analysis consist of climate type, dominant wind direction, temperature, precipitation, air content, pollution and soluble salts which influence the building. Micro environment analysis consist of age, height, architectural form, function, facade materials, material types, their characteristics and material structure system.

Data collected after the macro, meso and micro analysis and was used as a component while making the visual observations. Visual observations consist of the sunny and rainy-day conditions of the east facade. According to this conditions, agents of the deterioration have been analyzed by taking the feedback from the literature review. According to Kuş (2018), agents in the built environment very rarely act alone but neither work together. The effect of the agent occurs when a mechanism reveals its appearance.

Performance deteriorates at a rate depending on the environment, the design of the building, building materials, maintenance and usage (Song and Lim, 2016). In this case, since the building is at a very young age, it is not possible to visually observe the deteriorations but estimate them with the help of site analysis and visual observations.

Although all the visual information and the literature review provided, it is not possible to be certain about the future deteriorations.




Figure 1. A systematic approach.

2.3 Macro Environment

The building is located on the intersected corner of Portakal Çiçeği street and 1460 street in Antalya, Turkey. It is a seven storey-high residential building on the right with a distance of 8.40 meters, ten storey-high residential building on the back with a distance of 14 meters and front with a distance of 40 meters and two storey-car parking on the southwest with a distance of 21.5 meters. The main entrance faces to east (Figure 2). This facade always takes the sun directly without having any shading areas. The temperature and the light play a crucial role on materials. 1460 street and Portakal Çiçeği street have intense traffic. This causes air pollution which may create deterioration. The distance from the sea is 1 km and the height of the building from the sea is 22.5 m. The pedestrian roads and the vegetation around the building can be seen in Figure 3. There is an open area in front of the main facade. There are also car parking areas on the east and the west facade.



Figure 2. East facade of the building.

2.4 Meso Environment

Antalya has a hot humid climate with rainy winters. The dominant wind direction is from northeast to southwest (Figure 3). The temperature changes 10°C to 35°C through the year. October, November and December are the months that take most of the rainfall (Holidayweather, 2018).

The air contaminates soluble salts because of the distance within the sea. This may cause material deteriorations by collaborating with the mechanism. According to SİM Project, Sulphur dioxide and particulate matter has been diagnosed in the air (Sürekli Eğitim Merkezi, 2019). Sulfur dioxide and its acid derivations are known to cause considerable damage to materials. The east and north facade is open whereas the south and west facade are in the shade caused by surrounding buildings. There isn't so many people around the building except the Wednesdays because of the local bazaar. The building welcomes the animals.




Figure 3. The site plan, the section of the site (on the left) and dominant wind direction and the movement around the building (on the right).

2.4 Micro Environment

The six-storey office building is three years old. It has a rectangular form with the dimensions of 42.50 meters to 18.95 meters. The height of the building is 18.60 meters. The facade materials of the modern designed building are ceramic, aluminum, glass, granite and wood composite (Figure 4). The properties of the materials can be seen on Table 1.



Figure 4. Facade materials of the building and the structure system of the materials.

| Materials | Color | Surface finish |
|----------------|-------------|----------------|
| Ceramic | beige | unglazed |
| Ceramic | brown | unglazed |
| Granite | black | polished |
| Aluminium | white | polished |
| Wood composite | white | flat |
| Wood composite | light brown | flat |
| Glass | blue | flat |

Table 1. Properties of the facade materials.

Steel truss metal panel curtain wall system has been used for the facade system. A cross or vertical steel truss is installed on the structure first. Then, a panel is fixed to the steel truss. Finally, the vertical and horizontal joints between the panels are filled with back-up materials and then finished with sealant. No anchorage system and no joints can be seen from the external (Figure 4) (Song and Lim, 2016). The corner adjoining parts of the granites are unpolished. This part may take water and air to the inside and different types of deteriorations may occur.

3 Analysis

3.1 Visual Observation Information

For the case study, visual observations are made. The observations took two hours from 12.00 to 14.00. The materials on the east facade have been examined according to their instant conditions in a sunny day and in a rainy day (Table 2). Also, future deterioration problems are discussed.

| | Sunny day conditions | Rainy day conditions |
|-----------------|----------------------|----------------------|
| Observation day | 10.11.2018 | 17.11.2018 |
| Climate type | Winter | Winter |
| Temperature | 17°C | 14°C |
| Humidty | 43% | 86% |
| Wind direction | NE to SW | NW to SE |
| Wind speed | 3 km/h | 21 km/h |
| Rain ration | 0% | 70% |

Table 2. Visual observation conditions.

According to sunny-day and rainy-day conditions shading areas of the building have been examined. The facade of the building takes most of the sun except upper part of the facade of the ground floor in a sunny day, while it is totally in shade in a rainy day.

3.2 Agents, Mechanisms and Effects

Agents of deteriorations have been analyzed while making environmental analyses. 5 types of agents have been observed. These agents are grouped as; physical agents (temperature, moisture, light and wind), chemical agents (water, air, salts), biological agents (plants, birds, mold), design decisions, vandalism.

There exist 4 major typical mechanisms of deterioration, which lead to failure. These are grouped as; mechanisms caused by material properties, mechanisms caused by material structure properties, environmental mechanisms, construction related mechanisms.

A review of the causes of failure identified twelve of the most frequent sources of deterioration in facade materials are; dirt and dust accumulation, spalling, biological colonization, staining, corrosion, efflorescence, gypsum crust, cracks and breakage, discoloration, UV degradation, chipping, scratches. Agents, mechanisms and effects of the deterioration for each facade material can be seen in Table 3.

4 Results and Discussions

In this study, visual observations have been made to determine the future deteriorations. Since the building is only three years old, only the dirt deposition and the discoloration on the surface of the granites and discoloration on the WPC's caused by the rain have been observed. Expected deteriorations of the materials are discussed below.

Dirt and dust deposition occur on the cracks and on the surfaces of the panel with the help of the wind. High traffic areas cause great accumulation of dirt (Museum Management Program, 2018). The east facade is located on one of the most intense traffic areas. Dirt and dust deposition would be seen on the granite columns in the future. Wind can bring salts in the

air to the panel surface which can cause spalling (Museum Management Program, 2018). Spalling couldn't be seen on the front side of the columns. But it is seen on the north side of the columns. The reason is, the east side takes the sun more than the north side and can easily dry whereas the north side is always on shade. Biological agents such as bacteria, algae, fungi, and moss grow on stone surfaces and cracks with the help of humidity (Museum Management Program, 2018). The lower side of the columns can easily deteriorate because they are exposed to water more than the higher parts. Color changes on the panel surfaces may be caused by the design decisions. The sun plays an important role for this type of deterioration. This may also effect visual aesthetics (Mauko *et al.*, 2006).

Bowing and expansion due to temperature changes (Grelk *et al.*, 2007) may occur on the front side of the columns with the help of the temperature. Staining from water absorbtion or vapour condensation may occur on granite (ICOMOS, 2019). The corners of the granite are capable of water intake. Corrosion occurs when the chemical reactions happen (Shaw and Kelly, 2006). The corners of the granite have started to corrode and may cause structural problems in the future. Ceramics may contain soluble salts that can crystallize at or near the surface and destroy the panel (Museum Management Program, 2018). The adjoining parts of the ceramics are capable of salt intake. So, the efflorescence is possible.

Because of the location of the facade, air pollution may cause wet deposition where there is no rain-wash. This may cause gypsum crust (Agnes *et al.* 2012). Observations after the rain showed that, some part of the ceramics dry longer than the other parts. Condensation can lead to mold growth, noxious odors and deterioration of building finishes of the panels (Campante and Paschoal, 2002). Biological activity would be seen on the cracks of the ceramics (Agnes *et al.* 2012). Cracking occurs when thermal movement isn't provided (Goldberg, 2002).



Figure 5. Facade of the building (on the left), facade of the building in 30 years (on the right).

The panels would be affected by the temperature. It is clearly seen that no expansion joint was used, either vertical or horizontal. This may cause cracks and/or breakage even falling of the panels. Corrosion may occur on the metal structural supports and anchors of ceramic tiles (Campante and Paschoal, 2002). The panel joints may easily take water and air inside of the structure. Color changes create visually unproper aesthetic that can be seen on the ceramic tiles (Song and Lim, 2016). The reason of this can be dirt deposition which comes with the wind. Biological agents may use wood as a food source or for living with the help of water intake from the cracks or joints. This may cause weight loss of the panel (Morrell *et al.*, 2010). The WPC's on the east facade can easily take water from the rain. It is clearly seen that air pollution

came with the rain and created a color change at the surface. Because of the absorption characteristics of the WPC's moisture may cause damage of the material especially on the shading areas (Morrell *et al.*, 2010). The lower parts of the wood composite look better than the upper parts. It is probable that the upper parts would have a mechanical degredation in the future. Especially in the summer, the sun plays an important role. Wood absobs the UV lights. This causes loss of surface quality and change in the mechanical properties. UV degradation would be seen at the WPC's especially on the unshaded areas in the future.

Table 3. Agents, mechanisms and effects of the deteriorations.

| | Agents | Mechanisms | Effects | |
|-------------------|-------------------|------------------------------------|-----------------------------|--|
| E | Wind | Pollution caused by traffic | Dirt and dust accumulation | |
| | Moisture + wind | Salts on the surface | Spalling | |
| Z | Mositure + wind | Cracks | Biological colonization | |
| GRANITE | Design decisions | Sun | Color changes | |
| 5 | Temperature | No gaps between the panels | Bowing and expansion | |
| | Moisture | Panel joints | Staining | |
| | Air + water | Panel joints | Corrosion | |
| | Agents | Mechanisms | Effects | |
| CERAMIC | Soluble salts | Adjoining parts of the ceramic | Efflorescence | |
| | Design decisions | Air pollution | Gypsum crust | |
| | Moisture | Shading areas | Mold growth, Noxious odors | |
| | Temperature | No gaps between the panels | Cracks, Breakage | |
| | Air + water | Panel joints | Corrosion | |
| | Wind | Air pollution | Discoloration | |
| DD P. | Agents | Mechanisms | Effects | |
| | Biological agents | Water intake from the cracks | Weight loss of the material | |
| WOOD COMP. | Wind | Air pollution | Discoloration | |
| ≥ ⊃ | Moisture | Absorption characteristics of wood | Damage | |
| | Light | The color of the panels | UV degradation | |
| ALU MINI UM | Agents | Mechanisms | Effects | |
| | Air + water | Profile properties | Corrosion | |
| | Design decisions | Sun | Color changes | |
| GLASS | Agents | Mechanisms | Effects | |
| | Wind | Design decisions | Breakage | |
| | Birds | Structural problems | Chipping | |
| 5 | Human related | - | Scratches | |
| | Moisture | Application failures | Discoloration | |

Because of the design decisions, wind cause breakage of the glass panels which are not in a proper location of the facade (Honfi *et al.*, 2014). This may occur on the northeast side of the building because of the dominant wind direction. Birds cause chipping on the edges of the panels arised from the structural problems (Honfi *et al.*, 2014) This may occur on the upper parts of the façade. Vandalism may occur on the lower parts of the building on glass. Cleaning the panels with inappropriate materials may lead to deterioration. Moisture may ruin the mechanical and physical properties of stone and this causes discoloration. Since most of the building gets rain-washed, the glass panels can easily lose their visual aesthetics.

The method presented in this paper was developed as a tool for the prediction of the service life of building components. Deteriorations have been analyzed by a systematic approach using environmental analysis, visual observations and literature review. It is clearly seen that, deteriorations on the facade of the building will occur in the future (Figure 5).

Acknowledgement

This research has been supported by a PhD class called Performance of Building Elements Under Environmental Effects given by Professor Doctor Hülya Kuş at İstanbul Technical University. I thank her for comments that greatly improved the study.

ORCID

Nil Kokulu: https://orcid.org/0000-0002-7057-7601

References

- Agnes, B., Toth, M., Bajnoczi, B. and Szabo, C. (2012). Deterioration of Building Ceramics by Environmental Factors, A case study on Zsolnay Ceramics from the Museum of Applied Arts (Budapest), *Geosciences and Engineering*, 1(2), 7–14.
- Campante, E. and Paschoal, J. (2002). Durability of Facades with Ceramic Coverings, *IX International Conference on Durability of Building Materials and Components*, Brisbane, Australia, 60, 1-10.
- Goldberg, R.P. (1994). The Effects and Control of Moisture in Ceramic Tile Facades, *III World Congress on Ceramic Tile Quality*, Castellon, Spain, 231-247.
- Grelk, B., Christiansen, C., Schouenborg, B., Malaga K., Hoigard, K., Scheffler, M. and Dean, S.W. (2007). Durability of Marble Cladding-A Comprehensive Literature Review, *Journal of ASTM International*, 4(4). doi: 10.1520/JAI100857
- Holiday-weather (2018, December). *Antalya, Turkey: Annual Weather Averages*. https://www.holiday-weather.com/antalya/averages/
- Honfi, D., Reith, A., Vigh, L.G. and Stocker, G. (2014). Why glass structures fail? Learning from failures of glass structures, Louter, Bos, Belis & Lebet (Eds), Challenging Glass 4 & COST Action TU0905 Final Conference, London, England, Taylor & Francis Group. doi: 10.1201/b16499-109.
- ICOMOS (2019, January). *Illustrated Glossary on Stone Deterioration Patterns, Monuments and Sites*. https://www.icomos.org/publications/monuments_and_sites/15/pdf/Monuments_and_Sites_15_ISCS_Glossary Stone.pdf
- Khanam, Z., Singh V. and Zaidi, M.G.H. (2015). Effect of Environment on Corrosion Behaviour of Aluminium, *International Journal on Environmental Sciences*, 6(2), 281-286.
- Kuş, H. (2018). YAB 615E Performance of Building Elements under Environmental Effects: Agents, Mechanisms and Effects, PhD class, fall lecture notes.
- Marie, I. (2013). Perception Of Darkening of Stone Facades and The Need For Cleaning, *International Journal of Sustainable Built Environment*, 2(1), 65-72. doi: https://doi.org/10.1016/j.ijsbe.2013.09.001.
- Mauko, A., Mırtic, B., Mladenovic, A. and Grelk, B. (2006). Deterioration of the Granodiorite Facade, *Materials and Geoenvironment*, 53(1), 23-37.
- Morrell, J.J., Stark, N.M., Pendleton, D.E. and McDonald, A.G. (2010). Durability of Wood-Plastic Composites, 10th International Conference on Wood & Biofiber Plastic Composites, 16(3), 7-10.
- Museum Management Program (2018, December), Museum Handbook Part 1, Appendix P: Curatorial Care of Ceramic, Glass, and Stone Objects.
 - https://www.nps.gov/museum/publications/MHI/AppendP.pdf
- Shaw, B.A. and Kelly, R.G. (2006). *What is Corrosion?*, The Electrochemical Society Interface. Retrieved January 5, 2019 from https://www.electrochem.org/dl/interface/spr/spr06/spr06 p24-26.pdf
- Song, S.Y. and Lim, J.H. (2016). Evaluation of Alternatives for Reducing Thermal Bridges in Metal Panel Curtain Wall Systems, *Energy and Buildings*, 127(1), 138–158. doi: https://doi.org/10.1016/j.enbuild.2016.05.078
- Sürekli İzleme Merkezi (January 2019). http://www.havaizleme.gov.tr/Services/AirQuality.